

Helios

|                                                | 2026-1 |   |   |   |   | 2026-2 |   |   |    | 2026-3 |    |    |    | 2026-4 |    |    |    | 2026-5 |    |    |    | 2026-6 |    |    |    |
|------------------------------------------------|--------|---|---|---|---|--------|---|---|----|--------|----|----|----|--------|----|----|----|--------|----|----|----|--------|----|----|----|
|                                                | 2      | 3 | 4 | 5 | 6 | 7      | 8 | 9 | 10 | 11     | 12 | 13 | 14 | 15     | 16 | 17 | 18 | 19     | 20 | 21 | 22 | 23     | 24 | 25 | 26 |
| Hardware                                       |        |   |   |   |   |        |   |   |    |        |    |    |    |        |    |    |    |        |    |    |    |        |    |    |    |
| Helios                                         |        |   |   |   |   |        |   |   |    |        |    |    |    |        |    |    |    |        |    |    |    |        |    |    |    |
| Check I2C pullups                              |        |   |   |   |   |        |   |   |    |        |    |    |    |        |    |    |    |        |    |    |    |        |    |    |    |
| Driver board: No level shifter for I2C         |        |   |   |   |   |        |   |   |    |        |    |    |    |        |    |    |    |        |    |    |    |        |    |    |    |
| Calculate voltage-divider for "Enable" (...)   |        |   |   |   |   |        |   |   |    |        |    |    |    |        |    |    |    |        |    |    |    |        |    |    |    |
| Eval-RTC: Strange behaviour when battery (...) |        |   |   |   |   |        |   |   |    |        |    |    |    |        |    |    |    |        |    |    |    |        |    |    |    |
| Resistor between BAT and "Enable" is (...)     |        |   |   |   |   |        |   |   |    |        |    |    |    |        |    |    |    |        |    |    |    |        |    |    |    |